



2833 – 16<sup>th</sup> Avenue, Box 345, Hangar 17  
Markham, Ontario L3R 0P8  
Tel: 905-305-1655 Fax: 905-305-1645  
Email: gladeroute@fieldav.com

2450 Derry Road E., Hangar #2  
Mississauga, ON L5S 1B2  
Tel: 905 676-1230 Fax: 905 676-0977  
E-mail: c.cooper@fieldav.com

[www.fieldav.com](http://www.fieldav.com)

## **2007 LEAR 60XR**

**SERIAL NUMBER: 60-320**

**REGISTRATION: N229RP**



### **TOTAL TIMES**

TTAF & ENGINES:	507 Hours	Cycles: 413
APU: Honeywell RE100 (LJ)	442 Hours	Cycles: 800

As at January 11, 2010  
Recent A check (4-09) – On CAMP/CIMMS Systems  
Aircraft Meets European Certification Requirements

### **AVIONICS**

Collins Pro-Line 21 Avionics Suite:  
4 LCD 8 x 10" display units  
System Diagnostic Pages  
Dual AHRS-3000  
Enhanced GPWS, Windshear Detection  
Dual ADC-850D Air Data Computer  
TCAS II with Change 7  
Dual Collins FMS-5000  
Three Frequency 406 ELT  
Dual GPS-4000A Receiver  
Dual VIR-432 VHF Navigation  
Dual ADF-462  
Single ALT-4000 Radio Altimeter  
Dual DME-442  
Dual VHF-422C Communication, 8.33 Hz

Dual TDR-94 Mode S Transponder  
Dual RTU-4220 Radio Controller  
Dual Honeywell KHF-1050 HF  
Single Digital Autopilot  
Dual 1,500 VA Static Inverters  
Maintenance Diagnostic System  
CAT II Capable  
RVSM Capable  
Rockwell Collins Datalink (with 3<sup>rd</sup> VHF)  
Cockpit Voice Recorder (Exchange)  
Rosemount Ice Detection System  
Rockwell Collins TWR-850 Radar Enhanced Weather  
Radar (Exchange)  
3D FMS Maps  
Dual FSU with Electronic Charts  
Universal Weather (Dual FSU Configuration)  
Enhanced Map Overlays (Dual FSU Configuration)



### **EQUIPMENT**

Cockpit Speaker Mute  
Third Emergency Battery  
Pulsating Recognition and Landing Lights  
Tail Illumination Package  
Dual Rechargeable Flashlights  
Emergency Lighting Package

### **INTERIOR**

New factory leather on all seats (4-09)  
New Executive Floor Plan A (8 Passengers): 4 Single Seats with Fwd RH 3-place Divan  
Aft Lavatory with Belted Toilet Seat  
Stand-up Cabin through Recessed Aisle  
Forward Coat Closet  
2 Bi-Fold Executive Tables  
Seats Swivel and Recline  
Large Forward Left Hand Side Galley  
ICS-200 Iridium Dual Channel Telephone System (wireless handsets)  
Wood Veneer Package – High Gloss  
Dual Hot Liquid Containers  
LED Lighting throughout the Cabin  
Dual Drink Holders  
Satin Nickel Plating on Exposed Metal  
Window Shades  
Cabin Management System  
Cabin Stereo (10-disc Changer CD Player)  
Auxiliary Cabin Heater

Sink with Heated Water  
Vanity Cabinet with Mirror  
Lavatory Storage Space  
Heated Aft Baggage Compartment  
115V AC Outlets  
Microwave Oven  
XM Radio (US only)  
Cabin Video System  
Single DVD  
Airshow 410 World-Wide Map Coverage  
15.1" (38 cm) Forward Video Monitor  
Plated Metal Inlay on Sidewalls

### **EXTERIOR**

New factory paint (4-09)  
Allover White with Light and Medium Blue Stripes

### **WARRANTIES**

Parts and components manufactured by Lear  
5 years from aircraft delivery  
Rockwell Collins avionics  
Other Avionics  
Engines  
APU  
  
Paint and interior  
Other vendor components



5 years from aircraft delivery  
2 years from aircraft delivery  
5 years/2,500 hours from aircraft delivery  
2 years/1,500 airframe flight hours from  
Aircraft delivery  
2 years from aircraft delivery  
2 years from aircraft delivery